Subject: Performance of Hurricane Wind Ventilators at M/s Badve Autocomp P. Ltd., Chakan – Survey of customer satisfaction.

I came yesterday from Delhi to Pune and visited M/s Badve Autocomp P. Ltd., Chakan, as I wanted to survey the performance of Hurricane Turbines in an intense welding shop for submitting reference to prospective customers.

We understand that M/s Badve, Aurangabad is in discussion with you for more ventilators for expansion projects and therefore I would like to submit the survey report to you so that a positive environment can be created while discussing their additional requirements.

S. No.	Description	Frame Plant	Silencer Plant
1	Size of shed (approx.)	48m * 20 m * 10 m	80 m * 40 m * 10 m
2	No. of 24" Hurricane 600 ventilators	25 Nos.	56 Nos.
3	No. of Welding Stations	100 – 125	100 - 125
4	No. of persons	150 – 200	200 - 250
5	Other ventilation systems installed	1.) Gravent	1.) Exhaust hoods
		2.) Exhaust hoods	
6	Observations	Lot of smoke	Lot of smoke
		generated. Partly	generated. Partly
		collected by hoods,	collected by hoods,
		balance moves up.	balance moves up.
7	Smoke concentration stalled at ground	None	None
	level		
8	Smoke concentration stalled at roof level	None	None
9	Heat Concentration	None	None
10	Suffocation	Nil	Nil
11	Feeling when entering the plant in the	Good	Good
	morning		
12	Overall comfort level	Excellent	Excellent
13	Visibility during day / night	100 % / 100 %	100 % / 100 %
14	Water leakage	Nil	Nil
15	Any complaints	None	None
16	Is quantity sufficient	Required in loft area	Yes
17	Would recommend to other customers	Yes	Yes
18	Would like to re-order for own plants	Yes	Yes

It has always been our claim and supported by our collaborators and other test results that the Hurricane 600 is an excellent machine which provides a very strong suction at the top and will never fail in its duty.

We wish you the best and continue to look forward to your valuable support and that of your esteemed customers.

Yours Sincerely,

Sd/-Nirmal Khandelwal Director